


□□□□

□□□□	SF6927
□□□□□□□□	3.5mm
□□□□□□□□	2.0mm
□□□□	100g±20%
□□□□□□□□	0.5±0.2mm
□□□□□□□□	SUS303
□□	□□□□□□□□□□
□□□□□□	□□□□□□□□
□□□□□□	□□□□□□□□
□□□□□□□□□□□□	OEM □ ODM
MOQ	100□
□□□□□□	□□□□□□□□□□□□
□□□□	100% T/T□□□□
□□	□□□□□□□□□□□□ 5 □ 10 □

□□ □□□□□□



□□ □□



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



## Measuring Equipment >



### Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



