


□□□□

□□□□	SF5067
□□□□	3A
□□□□□	≤50mΩ
□□□	100g±20g
□□□□□□□	1.0mm
□□□□□□	Ph□□□□□□□□
□□	□□□□□□□
□□□□□	□□□□□□□
□	SUS
□□□□□□□□□□	OEM □ ODM
MOQ	100□
□□□□□	□□□□□□□□□□□□
□□□	100% T/T□□□
□□	□□□□□□□□□□ 5 □ 10 □

□□ □□□□□



材质与弹力:

1. 外套: 黄铜镀金
2. 针头: 磷铜镀金
3. 尾针: 黄铜镀金
4. 弹簧: 不锈钢线

技术要求:

1. 额定电流: 3A
2. 额定电阻: ≤50mΩ
3. 开关距离: 1.0mm
4. 开关弹力: 100g±20g

□□ □□



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



Measuring Equipment >



Measuring Equipment:

- 1. Agilent current testing;
- 2. Quadratic element measurement
- 3. Load Curve Meter
- 4. Bond Test
- 5. Life Fatigue Test



