


□□□□

□□□□	SF5067
□□□□	3A
□□□□□□□□	□50mΩ
□□□□	100g±20g
□□□□□□□□	1.0mm
□□□□□□	PH□□□□□□□□□□
□□	□□□ã □ã □□□
□□□□	□□□ã □ã □□□
□	SUS
□□□□□□□□□□	OEM□□&□□□□ODM
MOQ	100□
□□□□□	□□□□□□□□□□
□□□□	□□□□ 100% T/Tbing
□□	5-10 □ □□□□□□□□□□ □ □□□

□□ □□□□□□



材质与弹力:

1. 外套: 黄铜镀金
2. 针头: 磷铜镀金
3. 尾针: 黄铜镀金
4. 弹簧: 不锈钢线

技术要求:

1. 额定电流: 3A
2. 额定电阻: ≤50mΩ
3. 开关距离: 1.0mm
4. 开关弹力: 100g±20g

□□ □□□□



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



Measuring Equipment >



Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



