



000 20100 000 00 00 0000 000000. 0 00 0000 0000 000 0000 0



- 1. PCB, ICT, FCT [[[[] []
- 2. 00 000
- 3. 00 0000 00 0 00
- 4. 000 0

Production Flow (生产流程)









1. raw material warehouse 2. Lathe workshop

3. Assemble workshop







4. Quality inspection

5. Finished products

6. Packing

Measuring Equipment >











Measuring Equipment:

- 1. Agilent current testing;
- 2. Quadratic element measurement
- 3.Load Curve Meter
- 4.Bond Test
- 5.Life Fatigue Test