□□□□□□□□□□□□□□□□

□□□□

SFENG
The China's The World's

□□□□

□□□□□□□□□□□□□□□

□□□□□□□□

1. PCB,ICT,FCT□□□

2. pogo pin□□□

3□□□□□□□□□

4.□□□□□

□□□□

Production Flow (生产流程)

SFENG
The China's The World's

1. raw material warehouse

2. Lathe workshop

3. Assemble workshop

4. Quality inspection

5. Finished products

6. Packing

□□□□

Measuring Equipment

Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test