


□□ □□

□□ □□	SF5067
□□ □□	3A
□□ □□	50mΩ □□
□□□ □	100g±20g
□□□ □□	1.0mm
□□□	Ph, Ni □□
□	□□, □ □□
□□ □	□□, □ □□
□	SUS
□□□□ □□	OEM & ODM
MOQ	100PCS
□□□	Plastic bag, carton box
□□	□□ □ 100% T/T
□□ □□	□□□□ □□ □ 5~10□

□□ □□



材质与弹力:

1. 外套: 黄铜镀金
2. 针头: 磷铜镀金
3. 尾针: 黄铜镀金
4. 弹簧: 不锈钢线

技术要求:

1. 额定电流: 3A
2. 额定电阻:  $\leq 50\text{m}\Omega$
3. 开关距离: 1.0mm
4. 开关弹力:  $100\text{g} \pm 20\text{g}$

□□ □□



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



## Measuring Equipment >



### Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



