



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection




5. Finished products



6. Packing



Measuring Equipment >



Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



1. PCB/ICT/FCT
2. Pogopin
3. BGA
4. LM/QZ/VZ
- 5.
6. Terminal&receptacle/socket;
- 7.





1984 50

□□ □□

1. □□□□24□□□□□□□□□□
2. □□□□□□□□OEM□
3. □□□□□□□□□□□□□□□□□□

