




L112-H1.5



L112-JT1.0*2.0



2. OEM

3.

4.



1. PCB ICT FCT

2. Pogo pin

3. BGA

4. QZ VZ LM

5.

6. /

7. 30# OK POM



1. Raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



A5: [Placeholder]

Q6. [Placeholder]

A6: [Placeholder]

Q7. [Placeholder] **OEM** [Placeholder] **ODM** [Placeholder]

A7: [Placeholder] OEM/ODM [Placeholder]

Q8. [Placeholder]

A8: [Placeholder]