


- 材料
- 規格
- 檢驗

此圖為 Pogo pin 之規格圖，請參閱此圖之尺寸及公差。如有任何疑問，請洽本公司技術人員。

此圖為 Pogo pin 之規格圖，請參閱此圖之尺寸及公差。



1. PCB ICT FCT 測試
2. Pogo pin 測試
3. BGA 測試
4. QZ VZ 測試 LM
5. 測試 30# OK POM

SFENG
The China's The World's



SFENG
The China's The World's



SFENG
The China's The World's



SFENG
The China's The World's





Production Flow (生产流程)



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop




4. Quality inspection




5. Finished products



6. Packing



Measuring Equipment >



Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test