


□□□□

□□□□	SF4685
□□□	□□2.36×□□49.0mm
□□	□□□□□:BeCu□□□□□□□□□□□□□□ □□□□:□□□□□□□□□□□□□□□□□□□ □□□□□:SUS □□□□□□□□Ph□Au □□□□
□□□□□□□□	1.7±0.2mm
□□□□□□□□	5.2mm
□□□□□□ □□	4.2mm
□□□□	230±20%gf@ 4.2mm
MOQ	100□
□□□□	T/T
□□	□□□□□□□□□□□□ 5 □ 15 □

□□ □□□□□□



□□ □□



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



Measuring Equipment >



Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



