

- 銅 銅管 銅 銅 銅 SF-2.0x7.0







1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing

□□□ □□ □□


1. PCB, ICT, FCT □□□ □

2. □□ □ □□□

3. □□ □□□ □□ □ □□

4. □□□ □□□ □□□□ □

Measuring Equipment >



Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test