

□□□□


□□	SFENG
□□□□	SF-P100
□□	□□
□□	□□
□□	SUS□□□□
□□	200□
□□□□	6.40□0.2520"□
□□	3A
□□	50mW
□□□□	2.54□0.1000"□
□□□□□	1.70□0.0670"□/ 1.75□0.0689"□
MOQ	100 □
□□□□	□□□□7□□□□

□□□□

SF-P100



SF-P100-E



Probe specifications SF-P100(技术规格)

- Recommended minimum center(最小间距): 2.54mm(.1000")
- Mounting hole size(钻孔尺寸):
压克力: 1.70mm(.0670")
电木板、玻璃纤维板: 1.75mm(.0689")
- Full travel(行程): 6.40(.2520")
- Spring force(弹簧压力): 200g
- Materials and finishes(材料及涂饰):
Plunger:Be Cu,Rh plated; SK4,Rh plated
Barrel:Brass,Gold plated
Spring:Stainless steel
- Current ration(额定电流): 3A(安培)
- Contact resistance(接触电阻): 50mΩ(毫欧姆)

www.shengfengdz.com







□□□□□□□□□□LM□□QZ□VZ□□;

□□□□□□□□□□□□□□;

□□□□□;□□/□□;

□□□□□□□□□□30□OK□□□□□□□□POM□□□□□□

□□□□

Spring exhausted tester	DC power supply	Current resistance tester
		
Microscope	Tensile strength tester	Spring tester
		

□□□□

