


□□ □□

| | |
|-------|---------------------------------|
| □□ □□ | SF3653 |
| □□ | 3.0mm |
| □□ | $\Delta T < 20^{\circ}\text{C}$ |
| □□□ □ | 185g |
| □□□ | 5Amp |
| □□ | $< 10\text{m}\Omega$ |
| MOQ | 100PCS |
| □□ | □/□ |
| □□ □□ | □□□□ □□ □ 5~10□ |

□□ □□



□□ □□



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



Measuring Equipment >



Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



