


00 00

000 0000 000 00 0000 000000. 00 00 00 000 0 00/00 0000 0000 000 0 00 00 0000 0000 000 00 00 000000 000 0 0 000.

00 00 000 000(0: 000 0000) 00000 0000 000000 00 0000 0000 000 0 00000. 00000 00 **INGUN** 0000 00000 00 "0000"00 000000 00 00000(00).

00 00	SF-1.67x44
00	001.67*44mm
00	0000: Becu, Gold 00 000:000, 0 00 Insulation 000:PEEK 0: SUS304
0000 00	1.0mm
00 00	3A
00000	100 00
MOQ	100PCS
00	T/T
00 00	0000 00 0 5-150

00 00



00 00



1. raw material warehouse



2. Lathe workshop



3. Assemble workshop



4. Quality inspection



5. Finished products



6. Packing



## Measuring Equipment >



### Measuring Equipment:

1. Agilent current testing;
2. Quadratic element measurement
3. Load Curve Meter
4. Bond Test
5. Life Fatigue Test



